


**530-4015 HIGH, LOW PRESSURE PROTECTION SWITCH KIT  
(STANDARD THREAD 3/8" X 24)**

**ELIMINATES SUPER HEAT SWITCH & THERMO FUSE**



**EVACUATE SYSTEM, REMOVE HPRV VALVE. INSTALL COPPER  
WASHER ON SWITCH AND INSTALL IN HPRV VALVE PORT  
(TORQUE 145 IN. LBS) CONNECT 1 WIRE OF PIG TAIL TO  
CLUTCH GREEN WIRE AND 1 WIRE TO THERMOSTAT POWER  
WIRE.**